W-0198-001

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

	T OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER IDENTIFICATION NU			TIPLE CONSTRUCTION NG 01 - BUILDING 0101	(X3) DATE SURVEY COMPLETED
		495386		B. WING_		02/07/2018
	ROVIDER OR SUPPLIER			ESS, CITY,	STATE, ZIP CODE	
	GTON PLACE AT B	OTETOURT COMM		MMONS I	PARKWAY 24083	
TAG	(EACH DEFICIENCY MUST OR LSC IDE	TATEMENT OF DEFICIENCE BE PRECEDED BY FULL R NTIFYING INFORMATION)	EGULATORY	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LDBE COMPLETION
K 211 SS=F	1-story protected we The attic space is so by a 2-hour rated he building is separate. Construction Type: Sprinkler Status: The 13 wet and dry pipe supplied by municipe. An unannounced LS survey was conduct 02/07/18 in accorda Regulation, Part 483 Term Care Facilities for compliance using regulations. The fact with the Requirement and Medicaid. The findings that fol non-compliance with Regulations, 483.70(a) et seq (Lift Means of Egress - CCFR(s): NFPA 101 Means of Egress - CAIsles, passageways exit locations, and a with Chapter 7, and continuously mainta full use in case of er 18/19.2.2 through 18 18.2.1, 19.2.1, 7.1.1 This REQUIREMEN	cture: The structure is cood frame building of eparated from the liver or control assembly. It does not be a systems. The systems of the control of the cont	n a slab. ring area The cones. I by NFPA ms are cation ugh Federal Long rveyed sting) liance Medicare charges, rdance s is uctions to odified by enced	K 211	This plan of correction constitued Credible Allegation of Complian Preparation and/or execution of of correction does not constitute admission or agreement by the of the conclusion set forth in the statement of deficiencies. The Correction is prepared and/or esolely because it is required by vision of federal and state laws. Maintenance Director or designatest all fire rated door assemblies annually and complete a report findings. Annual inspections of fire rated assemblies to ensure they work properly to be completed.	te this plan te provider e Plan of xecuted the the door
:/\ A		The second of the second secon		and the state of t	111 bala	(X6) DATE

any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA **IDENTIFICATION NUMBER:** (X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING_

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE 290 COMMONS PARKWAY

	DALEV	/ILLE, VA	PARKWAY 24083	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	Continued From page 1 by: Surveyor: 21761 Based on observation and interview, it was revealed the facility failed to test rated doors. This has the potential to affect all residents and staff throughout the facility, evidenced as follows; Findings include: On 02/06/18 at approximately 3:35 P.M., it was observed that documentation could not be provided for rated door periodic testing and inspection. The Director of Maintenance witnessed this evidence by observation and interview. Egress Doors CFR(s): NFPA 101 Egress Doors Doors in a required means of egress shall not be equipped with a latch or a lock that requires the use of a tool or key from the egress side unless using one of the following special locking arrangements: CLINICAL NEEDS OR SECURITY THREAT LOCKING Where special locking arrangements for the clinical security needs of the patient are used, only one locking device shall be permitted on each door and provisions shall be made for the rapid removal of occupants by: remote control of locks; keying of all locks or keys carried by staff at all times; or other such reliable means available to the staff at all times. 18.2.2.2.5.1, 18.2.2.2.6, 19.2.2.2.5.1, 19.2.2.2.6 SPECIAL NEEDS LOCKING ARRANGEMENTS Where special locking arrangements for the safety needs of the patient are used, all of the Clinical or Security Locking requirements are being met. In addition, the locks must be electrical locks that fail safely so as to release	K 222	Report of fire rated door assemblies will be reviewed by the QA committee. The QA committee will determine the need and duration of future audits. New locking device was installed. A subsequent random check of all doors was completed to insure proper operation. Bi-weekly inspections of all doors will be done monthly for three (3) months, then randomly thereafter. Reports on the facilities door inspections will be reviewed by the QA committee. The QA committee will determine need and duration of future audits.	3/19/2018

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING _____

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

	DALEVILLE, VA 24083				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 222	Continued From page 2 upon loss of power to the device; the building is protected by a supervised automatic sprinkler system and the locked space is protected by a complete smoke detection system (or is constantly monitored at an attended location within the locked space); and both the sprinkler and detection systems are arranged to unlock the doors upon activation. 18.2.2.5.2, 19.2.2.2.5.2, TIA 12-4 DELAYED-EGRESS LOCKING ARRANGEMENTS Approved, listed delayed-egress locking systems installed in accordance with 7.2.1.6.1 shall be permitted on door assemblies serving low and ordinary hazard contents in buildings protected throughout by an approved, supervised automatic fire detection system or an approved, supervised automatic sprinkler system. 18.2.2.2.4, 19.2.2.2.4 ACCESS-CONTROLLED EGRESS LOCKING ARRANGEMENTS Access-Controlled Egress Door assemblies installed in accordance with 7.2.1.6.2 shall be permitted. 18.2.2.2.4, 19.2.2.2.4 ELEVATOR LOBBY EXIT ACCESS LOCKING ARRANGEMENTS Elevator lobby exit access door locking in accordance with 7.2.1.6.3 shall be permitted on door assemblies in buildings protected throughout by an approved, supervised automatic fire detection system and an approved, supervised automatic sprinkler system. 18.2.2.2.4, 19.2.2.2.4 This REQUIREMENT is not met as evidenced by: Surveyor: 21761 Based on observation and interview, it was revealed the facility failed to maintain delayed	K 222			

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING ____

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

	DALE	VILLE, VA	24083	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 222	egress exits. This violation potentially affects 1 of 3 smoke compartments, evidenced as follows; Findings include: On 02/06/18 at approximately 4:25 P.M., it was observed during inspection that the egress door to the outside near room 611 delayed locking device was not initiating the count down or releasing after 15 seconds as marked when the door crash bar was pressed. The Director of Maintenance witnessed this evidence by observation and interview.	K 222	Courtward doors were lasted and	
K 293 SS=F	Exit Signage 2012 EXISTING Exit and directional signs are displayed in accordance with 7.10 with continuous illumination also served by the emergency lighting system. 19.2.10.1 (Indicate N/A in one-story existing occupancies with less than 30 occupants where the line of exit travel is obvious.) This REQUIREMENT is not met as evidenced by: Surveyor: 21761 Based on observation and interview made on 02/06/18, it was revealed the facility failed to provide proper exit signage. This violation potentially affects 2 of 3 smoke compartments, evidenced as follows; Findings include: On 02/06/18 at approximately 4:00 PM, it was observed during inspection the doors leading from the enclosed courtyards back into the		Courtyard doors were locked and access to courtyard will be limited to supervised usage until exit signage inside courtyard is in place. A subsequent random check of all exit doors was completed to insure proper exit signage is in use. Monthly inspections of all exit doors will be done monthly for three (3) months, then randomly thereafter. Reports on the facilities exit door inspections will be reviewed by the QA committee. The QA committee will determine need and duration of future audits.	3/19/2018



Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING _____

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

	DALEVILLE, VA 24083					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE		
K 293	building are not marked by exit signage inside the courtyards. The Maintenance Director witnessed this evidence through observation and interview.	K 293	Nurses station door at machanical many			
	Hazardous Areas - Enclosure CFR(s): NFPA 101 Hazardous Areas - Enclosure Hazardous areas are protected by a fire barrier having 1-hour fire resistance rating (with 3/4 hour fire rated doors) or an automatic fire extinguishing system in accordance with 8.7.1 or 19.3.5.9. When the approved automatic fire extinguishing system option is used, the areas shall be separated from other spaces by smoke resisting partitions and doors in accordance with 8.4. Doors shall be self-closing or automatic-closing and permitted to have nonrated or field-applied protective plates that do not exceed 48 inches from the bottom of the door. Describe the floor and zone locations of hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9 Area Automatic Sprinkler Separation N/A a. Boiler and Fuel-Fired Heater Rooms b. Laundries (larger than 100 square feet) c. Repair, Maintenance, and Paint Shops d. Soiled Linen Rooms (exceeding 64 gallons) e. Trash Collection Rooms (exceeding 64 gallons) f. Combustible Storage Rooms/Spaces (over 50 square feet) g. Laboratories (if classified as Severe Hazard - see K322) This REQUIREMENT is not met as evidenced by: Surveyor: 21761		Nurses station door at mechanical room will be replaced by outside vendor. A subsequent random check of all fire rated doors was completed to insure all labels are legible. Monthly inspections of all fire rated doors will be done monthly for three (3) months, then randomly thereafter. Reports on the facilities fire rated door inspections will be reviewed by the QA committee. The QA committee will determine need and duration of future audits. (Reference time waiver request dated 2/14/2018.)	5/18/2018		

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION
A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING ___

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

	DALEV	ILLE, VA	24003	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 353 SS=F	Based on observation and interview made on 02/06/18, it was revealed the facility failed to maintain Hazardous area doors. This violation potentially affects 1 of 3 smoke compartments, evidenced as follows; Findings include: On 02/06/18 at approximately 4:07 P.M., it was observed during inspection that the rated door to the Blue Ridge Nurses station mechanical room has an illegible rating label. The Maintenance Director witnessed this evidence through observation and interview. Sprinkler System - Maintenance and Testing		Item was removed and placed lower than the allowable 18 inches to the sprinkler deflector in the Occupational Therapy storage closet. A subsequent random check of all storage closets was completed in the facility. Monthly inspections of all storage closets will be done monthly for three (3) months, then randomly thereafter. Reports on the facilities storage closet inspections will be reviewed by the QA committee. The QA committee will determine need and duration of future audits.	2/7/2018

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING __

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

		ILLE, VA		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	Continued From page 6 Based on observation and interview, it was revealed the facility failed to maintain the sprinkler system, evidenced as follows; Findings include: On 02/06/18, at approximately 4:35 P.M., it was observed during inspection there is combustible storage closer than the allowable 18 inches to the sprinkler deflector in the Occupational Therapy storage closet. The Director of Maintenance witnessed this evidence by observation and interview. Corridor - Doors CFR(s): NFPA 101 Corridor - Doors Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas resist the passage of smoke and are made of 1 3/4 inch solid-bonded core wood or other material capable of resisting fire for at least 20 minutes. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. Corridor doors and doors to rooms containing flammable or combustible materials have positive latching hardware. Roller latches are prohibited by CMS regulation. These requirements do not apply to auxiliary spaces that do not contain flammable or combustible material. Clearance between bottom of door and floor covering is not exceeding 1 inch. Powered doors complying with 7.2.1.9 are permissible if provided with a device capable of keeping the door closed when a force of 5 lbf is applied. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or		Occupational Therapy door will be replaced by outside vendor. A subsequent random check of all fire rated doors was completed to insure proper closure. Monthly inspections of all fire rated doors will be done monthly for three (3) months, then randomly thereafter. Reports on the facilities fire rated door inspections will be reviewed by the QA committee. The QA committee will determine need and duration of future audits. (Reference time waiver request dated 2/14/2018.)	5/18/2018

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

(X4) ID PREFIX	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY	ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE	(X5) COMPLETION
TAG	OR LSC IDENTIFYING INFORMATION)	TAG	CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	DATE
K 363	Continued From page 7 of unlimited height are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.3, unless the smoke compartment is sprinklered. Fixed fire window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies. 19.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. This REQUIREMENT is not met as evidenced by: Surveyor: 21761 Based on observation and interview made on	K 363		
	02/06/18, it was revealed the facility failed to maintain corridor doors. This violation potentially affects 1 of 3 smoke compartments, evidenced as follows; Findings include:			
	On 02/06/18 at approximately 4:38 P.M., it was observed during inspection that the Occupational Therapy double doors to the corridor do not properly close due to a faulty coordinator, which prevents proper sequencing, and prevents the closing of the doors against the passage of smoke. These doors also appear to be damaged.			
	The Maintenance Director witnessed this evidence through observation and interview. Fire Drills CFR(s): NFPA 101	K 712		

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING _____

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE
290 COMMONS PARKWAY

	D/	ALEVILLE, VA	24083	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATOR LSC IDENTIFYING INFORMATION)	ID FORY PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 712	Fire Drills Fire drills include the transmission of a fire ala signal and simulation of emergency fire conditions. Fire drills are held at expected and unexpected times under varying conditions, at least quarterly on each shift. The staff is famili with procedures and is aware that drills are pa of established routine. Where drills are conducted between 9:00 PM and 6:00 AM, a coded announcement may be used instead of	rm ar rt	Fire Drill documentation revised to reflect more accurate timeline. Maintenance staff and department heads in-serviced on proper documentation requirements. Monthly inspections of all fire drill documentation be done monthly for three (3) months, then randomly thereafter.	
	audible alarms. 19.7.1.4 through 19.7.1.7 This REQUIREMENT is not met as evidenced by: Surveyor: 21761 Based on observation and interview, it was revealed the facility failed to properly documer fire drills. This has the potential to affect residents and staff throughout the facility, evidenced as follows;	2	Reports on the facilities fire drill documentation will be reviewed by the QA committee. The QA committee will determine need and duration of future audits.	2/14/2018
K 918 SS=F	Findings include: On 02/06/18, at approximately 3:15 P.M., it was observed during review of the fire drill records that fire drill documentation is incomplete. The Director of Maintenance witnessed this evidence by observation and interview. Electrical Systems - Essential Electric Syste CFR(s): NFPA 101 Electrical Systems - Essential Electric System Maintenance and Testing The generator or other alternate power source and associated equipment is capable of supply service within 10 seconds. If the 10-second criterion is not met during the monthly test, a process shall be provided to annually confirm to	K 918	New recording document for the generator to show all the required information was developed. Removed books obstructing the emergency generator annunciator panel view and access at the nurses station.	

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING __

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

DALEVILLE, VA 24083					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 918	Continued From page 9 capability for the life safety and critical branches. Maintenance and testing of the generator and transfer switches are performed in accordance with NFPA 110. Generator sets are inspected weekly, exercised under load 30 minutes 12 times a year in 20-40 day intervals, and exercised once every 36 months for 4 continuous hours. Scheduled test under load conditions include a complete simulated cold start and automatic or manual transfer of all EES loads, and are conducted by competent personnel. Maintenance and testing of stored energy power sources (Type 3 EES) are in accordance with NFPA 111. Main and feeder circuit breakers are inspected annually, and a program for periodically exercising the components is established according to manufacturer requirements. Written records of maintenance and testing are maintained and readily available. EES electrical panels and circuits are marked, readily identifiable, and separate from normal power circuits. Minimizing the possibility of damage of the emergency power source is a design consideration for new installations. 6.4.4, 6.5.4, 6.6.4 (NFPA 99), NFPA 110, NFPA 111, 700.10 (NFPA 70) This REQUIREMENT is not met as evidenced by: Surveyor: 21761 Based on observation and interview, it was revealed the facility failed to maintain the emergency power system. This has the potential to affect residents and staff throughout the facility, evidenced as follows; Findings include: 1. On 02/06/18, at approximately 3:22 P.M., it was observed during review of the generator		Maintenance staff was in-serviced on proper procedures to test generators and properly record the required information. Facility staff in-serviced on importance of having clear access to the panel. Inspection of generator testing log will be done monthly for three (3) months, then randomly thereafter. Inspection of panel will be done daily for 3 months, then randomly thereafter. Reports on the facilities generator testing log documentation and panel checks will be reviewed by the QA committee. The QA committee will determine need and duration of future audits.	2/8/2018	

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING_

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

	D	ALEVILLE, VA	24083	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATION) OR LSC IDENTIFYING INFORMATION)	ATORY PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 918	Continued From page 10 records the documentation does not indicate generator batteries electrolyte levels are bein checked. Reference: NFPA 110, 2012 Edition Section 9.1.3.1. 2. On 02/06/18, at approximately 4:11 P.M., it was observed during inspection there were be obstructing the emergency generator annunci panel view and access at the Nurses station. The Director of Maintenance witnessed this evidence by observation and interview.	ng n, t poks		
K 920 SS=F		led as of nity nal t for er as ient eral a ed for s of	Power adapter and power tap devices were removed. A subsequent random check for any power adapters and power tap devices was completed throughout the facility. Monthly inspections for power adapters and power tap devices will be done monthly for three (3) months, then randomly thereafter. Reports on the facilities power adapter inspections and power tap devices will be reviewed by the QA committee. The QA committee will determine need and duration of future audits.	2/7/2018

Printed: 02/28/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 0101

(X3) DATE SURVEY COMPLETED

495386

B. WING _____

02/07/2018

NAME OF PROVIDER OR SUPPLIER

CARRINGTON PLACE AT BOTETOURT COMM

STREET ADDRESS, CITY, STATE, ZIP CODE

	DALEVILLE, VA 24083				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 920	Continued From page 11 by: Surveyor: 21761 Based on observation and interview, it was revealed the facility failed to prevent improper power device use. This violation potentially affects one of three smoke compartments, evidenced as follows; Findings include: 1. On 02/06/18, at approximately 4:45 P.M., it was observed during inspection a non-approved power adapter was in use for the IT equipment in the Medical Records' Office. 2. On 02/06/18, at approximately 4:47 P.M., it was observed during inspection a portable power tap device was powered by another portable power tap device for the IT equipment in the Medical Records' Office. The Director of Maintenance witnessed this evidence by observation and interview.	K 920			