Printed: 07/01/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED		
		495320		B. WING			06/27/2019		
l l				TREET ADDRESS, CITY, STATE, ZIP CODE					
				CLINTWOOD MAIN STREET. ROUTE 607 PO BOX 909 WOOD, VA 24228					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)			(X5) COMPLETION DATE	
K 000			e II (000)	K 000					
	Description of structure: One Story, Type II (000) Sprinkler status: Fully Sprinklered, NFPA 13  An unannounced routine Life Safety Code survey was conducted on June 27, 2019 in accordance with 42 Code of Federal Regulation, Part 483: Requirements for Long Term Care Facilities. The								
	facility was surveyed for compliance using LSC 2012 Existing regulations. The facilinot in compliance with the Requirement Participation Medicare and Medicaid.		lity was		e e				
	The findings that fo non-compliance wit Regulations, 483.70 Fire.)	llow demonstrate h Title 42 Code of 0(a) et seq (life Safet	ty from		¥.				
	Hazardous Areas - CFR(s): NFPA 101	Enclosure		K 321					
	having 1-hour fire refire rated doors) or system in accordan When the approved	Enclosure re protected by a fire esistance rating (with an automatic fire ext ce with 8.7.1 or 19.3 I automatic fire extin ed, the areas shall b	n 3/4 hour inguishing i.5.9, guishing						
	separated from othe partitions and doors Doors shall be self- and permitted to ha protective plates that from the bottom of t	er spaces by smoke in accordance with closing or automatic ve nonrated or field- at do not exceed 48	resisting 8.4. -closing applied inches						
		at are deficient in RE							
LABORATÃO	Area Separation N/A a. Boiler and Fuel-F	ired Heater Rooms		IATURE	/ I a TIPLE			(X6) DATE	
CABORATOR	Y DIRECTOR'S OR PROVI	DERISOPPLIER REPRESE	MIATIVE'S SIGN	VATURE A	111 TITLE		11.	-717	

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Printed: 07/01/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 (X3) DATE SURVEY COMPLETED

495320

B. WING \_

06/27/2019

NAME OF PROVIDER OR SUPPLIER HERITAGE HALL CLINTWOOD STREET ADDRESS, CITY, STATE, ZIP CODE

1225 CLINTWOOD MAIN STREET, ROUTE 607 PO BOX 909

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 321	Continued From page 1	K 321	Corrective Action: K: 321	7-5-19	
	b. Laundries (larger than 100 square feet)		Corrective action taken for the	,,	
	c. Repair, Maintenance, and Paint Shops				
	d. Soiled Linen Rooms (exceeding 64 gallons)		Identified problem		
	e. Trash Collection Rooms				
	(exceeding 64 gallons)		The penetrations located at the fire wall		
	f. Combustible Storage Rooms/Spaces		separating the boiler room and the		
	(over 50 square feet)		Maintenance Office was sealed with 3M CP 25WB+ Intumescent (Red) fire rated		
	g. Laboratories (if classified as Severe				
	Hazard - see K322)		caulking		
	This REQUIREMENT is not met as evidenced				
	by:		Address how facility will identify		
	The Standard is not met as evidenced by:		Similar occurrences of the problem		
			A 100% audit/inspection was conducted on		
	Surveyor: 12956		all fire/smoke walls to identify any other		
			penetration that are not sealed.		
	Based on observation and staff interview, the				
	facility failed to maintain structural fire rating in		No other negative findings were noted		
	accordance with LSC Section 19.3.2.1. The		during the review		
	deficient pratice could affect 2 of 4 fire areas		571		
	including patients, staff and visitors in the event of		Identify measures/systemic changes		
	a fire due to the penetrations of the fire barrier not		to ensure deficient practice will not		
	being properly fire stopped.		recur.		
			The Maintenance Director will in-service		
	Findings Include;		any vendors/contractors that conduct		
	0, 07,0040 (1,5,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1		service to the plant that might involve		
	Observations on June 27, 2019 during the tour		drilling through fire/smoke walls as to the		
	from 9:00 am to 12:00 pm revealed that:		proper caulking to use when sealing		
	At approximation 10:15 am the fire barrier		penetration/s.		
	At approximately 10:15 am, the fire barrier		postolitudos, si		
	seperating the Mechanical Room from the Maintenance Office had some penetrations of the		Indicate how facility will monitor its		
	fire rated barrier wall above the ceiling of the		performance		
	Maintenance Office that were not firestopped on		A comprehensive life safety review of the		
	both sides of the fire barrier. An interview with the		facility by the Regional Facility Advisor and		
	Maintenance Director (DM) at the time of the		the Vice President of Engineering is		
	observation revealed that the DM was not aware		conducted annually. A review of the cited	1	
	that all of the penetrations had not been fire		violation will be conducted throughout the		
	stopped.		facility at that time		
	This finding was verified by the DM at the time of				

Printed: 07/01/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION
A, BUILDING 01 - MAIN BUILDING 01

(X3) DATE SURVEY COMPLETED

495320

B. WING \_\_\_\_

06/27/2019

NAME OF PROVIDER OR SUPPLIER

#### **HERITAGE HALL CLINTWOOD**

STREET ADDRESS, CITY, STATE, ZIP CODE

1225 CLINTWOOD MAIN STREET. ROUTE 607 PO BOX 909 CLINTWOOD, VA 24228

	CLINTWOOD, VA 24220						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	Continued From page 2 the observation and the Administrator at the exit interview on June 27, 2019 at 12:15 pm.  Utilities - Gas and Electric CFR(s): NFPA 101  Utilities - Gas and Electric Equipment using gas or related gas piping complies with NFPA 54, National Fuel Gas Code, electrical wiring and equipment complies with NFPA 70, National Electric Code. Existing installations can continue in service provided no hazard to life. 18.5.1.1, 19.5.1.1, 9.1.1, 9.1.2	K 321	Corrective Action: K: 511  Corrective action taken for the Identified problem  A knock panel protector was installed on the electrical panel located in the Mechanical Room to ensure there is no gaps in the panel face.  Address how facility will identify Similar occurrences of the problem  A 100% audit/inspection was conducted on all electrical panel boxes to insure compliance to NFPA 70  All negative findings were corrected.				
	This REQUIREMENT is not met as evidenced by: The Standard is not met as evidenced by: Surveyor: 12956  Based on observation and staff interview, the facility failed to maintain electrical equipment in accordance with the LSC Section 19.5.1, The deficient pratice could affect one of 4 fire barriers, patients, staff and vistors, due to the opening in the electric panel having an open breaker knock-out having been removed.  Observation on June 27, 2019 during the tour	×	Identify measures/systemic changes to ensure deficient practice will not recur. Maintenance Staff was in serviced by Regional Facility advisor on cited deficiencies. A copy of the in-service is on file.  Indicate how facility will monitor its performance A comprehensive life safety review of the facility by the Regional Facility Advisor and the Vice President of Engineering is conducted annually. Compliance to NFPA 70 is reviewed during this survey.				
	from 9:00 am to 12:00 pm revealed that:  At approximately 11:50 am, it was identified that the an electrical panel in the Mechanical room had an opening in the panel not provided with an approved knock-out plug where a new circuit breaker had been installed for a new unit heater.  An interview with the Director of Maintenance		-				

Printed: 07/01/2019 FORM APPROVED OMB NO. 0938-0391

GENTERST ON MEDICARE & MEDICARD SERVICES						CIVID NO	1 650-0561	
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) P		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED		
49532		495320		B. WING		06/27/2019		
NAME OF P	ROVIDER OR SUPPLIER		STREET ADDI	RESS, CITY, S'	TATE, ZIP CODE			
		OD				7 DO DOV 00	. 1	
				CLINTWOOD MAIN STREET. ROUTE 607 PO BOX 909 WOOD, VA 24228				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATÉ	
K 511	Continued From pa	age 3		K 511				
Kun	(DM) at the time of the observation revealed that the DM was unaware opening. This did not meet the requirements of NFPA 101 Sections 19.5.1 9.1.2 and NFPA 70.  These findings were verified by the DM at the		Kon					
	time of the observation and the Administrator at the exit conference on June 27, 2019.							
3							1	
- 1								
			-					
							1	
							4	
							1	
			. 1					
			j					
							1	