

## COMMONWEALTH of VIRGINIA

### Virginia Department of Fire Programs

Michael T. Reilly EXECUTIVE DIRECTOR

Brian M. McGraw, P.E. STATE FIRE MARSHAL

State Fire Marshal's Office Division 1 1005 Technology Park Drive Glen Allen, VA 23059-4500 Phone: 804/371-0220 Fax: 804/371-3367

09/13/2018

Mr. Matthew Farmer, Glenburnie Rehab & Nursing Center 1901 Libbie Ave Richmond, VA 23226

Dear Mr. Farmer

This concerns the unannounced recertification Life Safety Code survey of the referenced facility conducted 09/04/2018 in accordance with 42 Code of Federal Regulation, Part 483: Requirements for Long Term Care Facilities. The facility was surveyed for compliance using the Life Safety Code 2000 Existing regulation.

All institutional buildings must meet all applicable Life Safety Code (NFPA 101) requirements in accordance with the federal Long Term Care certification requirements issued by the Centers for Medicare and Medicaid Services (CMS), in order to participate in the Medicare/Medicaid programs. The findings listed on the attached form, CMS 2567, "Statement of Deficiencies and Plan of Correction", demonstrate non-compliance with Title 42 Code Federal of Regulations, 483.70(a) et seq Life Safety from Fire.

Prior to making expenditures to correct the noted deficiencies, you should have an approved plan of correction. It is strongly recommended that you check with local officials, since compliance with this report does not excuse you from complying with local codes and ordinances.

The federal LTC Enforcement Regulations remedies may be imposed by the Centers for Medicare and Medicaid Services (CMS) and/or the Virginia Department of Medical Assistance Services (DMAS) for any failure or continued failure to demonstrate compliance with both the Health and Life Safety Code requirements (Title 42, Code of Federal Regulations). For example, a Denial of Payment for New Admissions at the 90th day after a survey, or the Termination of the Provider Agreement at the 180th day after a survey, could be a result of uncorrected Life Safety Code citations as well as Health citations.

If any deficient practice is identified within either the Health or Life Safety Code requirements, a Plan of Correction (POC) developed by the provider must be returned to the surveying entity by 9/24/2918. To be considered acceptable, the POC must include five (5) components:

- 1. Address the corrective action taken for the identified problem
- 2. Address how facility will identify similar occurrences of the problem
- 3. Identify measures/systemic changes to ensure deficient practice will not recur
- 4. Indicate how facility will monitor its performance
- 5. Date of correction, not to exceed 45<sup>th</sup> day after the survey.

NOTE: If correction/compliance by the 45<sup>th</sup> day after the survey is not possible, the facility's POC must be accompanied by a Time-Limited Waiver request with appropriate justification. The waiver request and supporting documentation will be reviewed by the State Fire Marshal's Office and the Virginia Department of Health for a final recommendation to CMS. Please be aware, the timeline involved in the Time Limited Waiver request and final approval process does not delay the potential imposition of enforcement actions.

If concerns regarding a citation are not resolved, in accordance with §488.331, the facility has one (1) opportunity to question cited deficiencies through the current Virginia Department of Health's informal dispute resolution (IDR) process. To be considered, the IDR request must be received by the State Fire Marshal's Office within 10 calendar days of your receipt of the enclosed survey findings. An incomplete informal dispute resolution process will not delay the effective date of the imposition of any enforcement actions taken by CMS or DMAS.

#### Survey Results

The results of this survey are reflected on the enclosed Statement of Isolated Deficiencies, "A" Form and/or the Statement of Deficiencies and Plan of Correction, CMS 2567. All survey findings generated on these forms (including the most recent standard survey and any subsequent revisits or complaint investigations) constitute the facility's current survey report. In accordance with §483.10(g), the current survey report must be made available for examination in a place readily accessible to residents and is disclosable to all interested parties.

If you have any questions or if we may be of assistance to you, please call (804) 840-3523.

Sincerely,

F. Troy Bower

State Fire Marshal's Office

Franklin Troy Bower

Attachment

cc: file

DEPARTMENT OF HEALTH AND HUMAN SERVICES Printed: 09/13/2018 CENTERS FOR MEDICARE & MEDICAID SERVICES **FORM APPROVED** OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - BUILDING 01 (X3) DATE SURVEY COMPLETED 495391 09/04/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **GLENBURNIE REHAB & NURSING CENTER** 1901 LIBBIE AVE RICHMOND, VA 23226 (X4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY (EACH CORRECTIVE ACTION SHOULD BE (X5) COMPLETION DATE PREFIX OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) K 000 INITIAL COMMENTS K 000 Surveyor: 39900 Description of structure: The facility is a two story Type II (111). Sprinkler Status: Fully sprinklered - NFPA 13 An unannounced Standard Recertification Life Safety Code Survey was conducted on 9/4/18 in accordance with 42 Code of Federal Regulation, Part 483: Requirements for Long Term Care Facilities. The facility was surveyed for compliance using the LSC 2012 Existing regulations. The facility was not in compliance with the Requirements for Participation Medicare and Medicaid. The findings that follow demonstrate non-compliance with Title 42 Code of Regulations, 483.70(a) et seq (Life Safety from Fire.) K 100 General Requirements - Other K 100 SS=D CFR(s): NFPA 101 1. The Kitchen hood vents were all 9-4-18 General Requirements - Other cleaned the same day as the List in the REMARKS section any LSC Section 18.1 and 19.1 General Requirements that are not inspection survey. addressed by the provided K-tags, but are 2. There are no other hood vents deficient. This information, along with the other than Dietary. applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. 3. Hood Vents will be inspected This REQUIREMENT is not met as evidenced weekly to insure ongoing by: Surveyor: 39900 cleaning standards are met. Based upon observations the kitchen hood vents 4. Performance will be monitored were not properly kept clean per SFPC 609.3.3.1. by the Food Service Manager Findings include: on a weekly basis

On 9/4/2018, between 9:30am and 12:30pm, it LABORATORY DIRECTOR'S OR PROVIDER JUPPLIER REPRESENTATIVE'S SIGNATURE

MI other

amni strato

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

K 100

Printed: 09/13/2018 FORM APPROVED DMB NO. 0938-0391

CENTER	13 FUN MEDICANE	& MEDICAID SERV	IUES			OMB NO	0. 0938-039
O	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIE IDENTIFICATION NUI		1.	IPLE CONSTRUCTION NG <b>01 - BUILDING 01</b>	(X3) DATE S	SURVEY
		495391		B. WING_		09/0	14/2018
NAME OF P	ROVIDER OR SUPPLIER		STREET ADD	RESS. CITY.	STATE, ZIP CODE		
	JRNIE REHAB & NU	JRSING CENTER	1901 LI	BBIE AVE OND, VA	E		
(X4) ID PREFIX TAG	(EACH DEFICIENCY MUST	ATEMENT OF DEFICIENCIE FBE PRECEDED BY FULL I NTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	JI D RE	(X5) COMPLETION DATE
SS=D	was observed that to greasy.  Egress Doors CFR(s): NFPA 101  Egress Doors Doors in a required equipped with a late use of a tool or key using one of the folloarrangements: CLINICAL NEEDS CLOCKING Where special lockin clinical security need only one locking deveach door and provist rapid removal of occlocks; keying of all locking the same of the staff 18.2.2.2.5.1, 18.2.2.2 SPECIAL NEEDS LOW here special lockin safety needs of the polinical or Security Locking met. In additional security and the locked system and the locked constantly monitored within the locked spand detection system and detection system loors upon activation 8.2.2.2.5.2, 19.2.2.2 DELAYED-EGRESS	means of egress shall or a lock that requirements for discount of the patient are rice shall be permitted sions shall be made supants by: remote cocks or keys carried such reliable means at all times.  2.6, 19.2.2.2.5.1, 19.0 DCKING ARRANGE of arrangements for patient are used, all cocking requirements in, the locks must be all safely so as to reliable the device; the built vised automatic spring at an attended loca ce); and both the spins are arranged to unit.	all not be ires the unless of the used, don for the ontrol of by staff  2.2.2.6 MENTS the are ease ding is nkler d by a tion rinkler	K 100	1. The exit doors by the Kit bathroom and by the en breakroom magnetic loc repaired on 9-5-18 and r functioning as designed. 2. All exit doors are checke to ensure egress require are met. 3. Maintenance will maintainspections, monthly of a doors. 4. Compliance will be maintaby monthly inspections.	nployee ks were now are d daily ments in all egress	9-5-18
A	RRANGEMENTS	yed-egress locking	systems				

#### DEPARTMENT OF HEALTH AND HUMAN SERVICES Printed: 09/13/2018 CENTERS FOR MEDICARE & MEDICAID SERVICES FORM APPROVED OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION (X3) DATE SURVEY IDENTIFICATION NUMBER: A. BUILDING 01 - BUILDING 01 COMPLETED 495391 B. WING\_ 09/04/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **GLENBURNIE REHAB & NURSING CENTER** 1901 LIBBIE AVE RICHMOND, VA 23226 (X4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY) (X5) COMPLETION PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG DATE DEFICIENCY) K 222 Continued From page 2 K 222 installed in accordance with 7.2.1.6.1 shall be permitted on door assemblies serving low and ordinary hazard contents in buildings protected throughout by an approved, supervised automatic fire detection system or an approved, supervised automatic sprinkler system. 18.2.2.2.4, 19.2.2.2.4 ACCESS-CONTROLLED EGRESS LOCKING **ARRANGEMENTS** Access-Controlled Egress Door assemblies installed in accordance with 7.2.1.6.2 shall be permitted. 18.2.2.2.4, 19.2.2.2.4 ELEVATOR LOBBY EXIT ACCESS LOCKING **ARRANGEMENTS** Elevator lobby exit access door locking in accordance with 7.2.1.6.3 shall be permitted on door assemblies in buildings protected throughout by an approved, supervised automatic fire detection system and an approved, supervised automatic sprinkler system. 18.2.2.2.4, 19.2.2.2.4 This REQUIREMENT is not met as evidenced bv: Surveyor: 39900 Based upon observations there are 15 second time delay locks that restrict the full operation of the doors so occupants can egress to an exit. Findings include: On 9/4/2018, between 9:30am and 12:30pm, it was observed that the emergency egress door by kitchen bathrooms was not releasing after 15 seconds. On 9/4/2018, between 9:30am and 12:30pm, it was observed that the emergency egress door by the employee lounge was not releasing after 15

**Emergency Lighting** 

CFR(s): NFPA 101

seconds.

K 291

SS=D

K 291

Printed: 09/13/2018 FORM APPROVED OMB NO. 0938-0391

(X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - BUILDING 01 COMPLETED 495391 B. WING 09/04/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **GLENBURNIE REHAB & NURSING CENTER** 1901 LIBBIE AVE RICHMOND, VA 23226 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETION IEACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY PRÉFIX (EACH CORRECTIVE ACTION SHOULD BE **PREFIX** OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DATE DEFICIENCY) K 291 Continued From page 3 K 291 K 291 1. Emergency light inspections are **Emergency Lighting** Emergency lighting of at least 1-1/2-hour duration conducted weekly and new 9-4-18 is provided automatically in accordance with 7.9. batteries were installed in the 18.2.9.1. 19.2.9.1 two lights addressed in the This REQUIREMENT is not met as evidenced report, same day as the survey. Surveyor: 39900 2. All lights will be checked weekly Based upon observations there are areas that do and logs will be maintained by not have the required emergency lighting. Maintenance to record Findings include compliance. On 9/4/2018, between 9:30am and 12:30pm. 3. All Lights will be checked weekly during review of documentation it was observed to insure that they illuminate that there were no records of annual/monthly emergency light inspections. properly. 4. Monitoring of compliance will be On 9/4/2018, between 9:30am and 12:30pm, it was observed that the exit sign had a dead conducted by weekly battery at end of hallway 2nd floor by human inspections. resources. 1. 1. The doors to Human K 321 Hazardous Areas - Enclosure K 321 Resources, the Boiler room were SS=D CFR(s): NFPA 101 repaired the day of survey. The 9-4-18 Hazardous Areas - Enclosure door in the Kitchen prop was Hazardous areas are protected by a fire barrier removed the day of survey and having 1-hour fire resistance rating (with 3/4 hour fire rated doors) or an automatic fire extinguishing staff was instructed not to prop system in accordance with 8.7.1 or 19.3.5.9. open again. When the approved automatic fire extinguishing system option is used, the areas shall be 2. All doors will be checked separated from other spaces by smoke resisting Monthly to insure proper partitions and doors in accordance with 8.4. Doors shall be self-closing or automatic-closing closure. and permitted to have nonrated or field-applied 3. Audits conducted monthly. protective plates that do not exceed 48 inches 4. Maintenance will inspect from the bottom of the door. Describe the floor and zone locations of monthly for ongoing hazardous areas that are deficient in REMARKS.

compliance.

Printed: 09/13/2018 FORM APPROVED

STATEME	ENT OF DEFICIENCIES	(VI) PROVIDED/GURBIUM	- DIOLU	(X2) MUUTU	PLE CONSTRUCTION	OMB NO	O. 0938-039
	N OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		A. BUILDING 01 - BUILDING 01			SURVEY ETED
		495391		B. WING_			
	PROVIDER OR SUPPLIER		STREET ADD	RESS, CITY, S	TATE, ZIP CODE		04/2018
GLENB	URNIE REHAB & NU	RSING CENTER	1901 LI	BBIE AVE OND,`VA 2			
(X4) ID PREFIX TAG	(EACH DEFICIENCY MUST OR LSC IDEN	NTIFYING INFORMATION)	S REGULATORY	ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTIC CROSS-REFERENCED TO TH DEFICIENCY	ON SHOULD BE	(X5) COMPLETION DATE
K 321		ge 4		K 321			
	19.3.2.1, 19.3.5.9						
. I S	Area Separation N/A a. Boiler and Fuel-Fir b. Laundries (larger t c. Repair, Maintenand d. Soiled Linen Room e. Trash Collection Re (exceeding 64 gallons f. Combustible Storag (over 50 square feet) g. Laboratories (if class Hazard - see K322) This REQUIREMENT by: Surveyor: 39900 Based upon observation for maintained to provor fire resistant ratings There are doors that a atching, are damaged the required listing for collow smoke and hot gallows.	han 100 square feet ce, and Paint Shops is (exceeding 64 gal coms is) ie Rooms/Spaces issified as Severe is not met as evide ons hazardous area ide required separat for the hazardous are re not self closing and doors that do no	enced s are tion and areas. nd tot have				
O wasto	indings include: In 9/4/2018, between 9	ire rated storage rooms 2:30am and 12:30pm re rated door closer soom door at main door 30am and 12:30pm re rated door to the was held open with	om  n, it was lining n, it dry an				

Printed: 09/13/2018 FORM APPROVED OMB NO. 0938-0391

	NT OF DEFICIENCIES NOF CORRECTION	(X1) PROVIDER/SUPPLIE IDENTIFICATION NUI		1	TIPLE CONSTRUCTION NG 01 - BUILDING 01	(X3) DATE	SURVEY LETED
		495391		B. WING_		09/	04/2018
	PROVIDER OR SUPPLIER URNIE REHAB & NU	RSING CENTER	1901 LI	RESS, CITY, BBIE AVE OND, VA			
(X4) ID PREFIX TAG	(EACH DEFICIENCY MUST	ATEMENT OF DEFICIENCIE BE PRECEDED BY FULL ( NTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	II D BE	(X5) COMPLETION DATE
K 321	Continued From pa was observed that the Bradford was not lat	he rated soiled utility		K 321			
	Sprinkler System - N CFR(s): NFPA 101	Maintenance and Tes	sting	K 353			
	Sprinkler System - Mautomatic sprinkler a inspected, tested, ar with NFPA 25, Stand Testing, and Maintain Protection Systems. maintenance, inspector maintained in a securavailable.  a) Date sprinkler system superior with the system superior system superior with the syste	and standpipe systemed maintained in accordant for the Inspection of Water-based Records of systemention and testing are relocation and read stem last checked stem test	ms are ordance on, Fire design, lily				
	for any non-required system. 9.7.5, 9.7.7, 9.7.8, an This REQUIREMENT by: Surveyor: 39900 Based upon observat that the required main not being maintained missing/damaged in respective.	d NFPA 25 is not met as evidentiations of the sprinkler of the syst Ciling tiles were	enced				
i C V	Findings include: On 9/4/2018, betweer was observed that the n the stairwell on the On 9/4/2018, betweer was observed that the n the stairwell on the	ere were ceiling tiles 2nd floor. 19:30am and 12:30 ere were ceiling tiles	missing pm, it				
K 363 (	Corridor - Doors			K 363			

Printed: 09/13/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION
A. BUILDING 01 - BUILDING 01

(X3) DATE SURVEY COMPLETED

495391

B. WING

09/04/2018

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

### **GLENBURNIE REHAB & NURSING CENTER**

1901 LIBBIE AVE RICHMOND, VA 23226

	111011	MOND, VA	23220	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
SS=D  SS=D  I  I  I  I  C  C  C  W  W  in  de  pu  of  m  sh  ma  sn  wii  sp  res  fra  19.  and She	Continued From page 6 CFR(s): NFPA 101  Corridor - Doors Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas resist the passage of smoke and are made of 1 3/4 inch solid-bonded core wood or other material capable of resisting fire for at least 20 minutes. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. Corridor doors and doors to rooms containing flammable or combustible materials have positive latching hardware. Roller atches are prohibited by CMS regulation. These requirements do not apply to auxiliary spaces that do not contain flammable or combustible material. Clearance between bottom of door and floor overing is not exceeding 1 inch. Powered doors complying with 7.2.1.9 are permissible if provided with a device capable of keeping the door closed when a force of 5 lbf is applied. There is no inspediment to the closing of the doors. Hold open evices that release when the door is pushed or culled are permitted. Nonrated protective plates in unlimited height are permitted. Dutch doors eeting 19.3.6.3.6 are permitted. Door frames in all be labeled and made of steel or other aterials in compliance with 8.3, unless the noke compartment is sprinklered. Fixed fire indow assemblies are allowed per 8.3. In rinklered compartments there are no strictions in area or fire resistance of glass or mes in window assemblies.  3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, 485 ow in REMARKS details of doors such as fire tection ratings, automatics closing devices,	K 363	1. The door to Room # 121's closure latch was repaired day of survey.  2. Doors will be checked for proper closure by Maintenance on a monthly basis.  3. Inspections regarding proper room door closure will occur monthly.  4. Maintenance will monitor via monthly inspections.	9-4-18

**GLENBURNIE REHAB & NURSING CENTER** 

Printed: 09/13/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

495391

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - BUILDING 01

(X3) DATE SURVEY COMPLETED

09/04/2018

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

1901 LIBBIE AVE RICHMOND, VA 23226

	RICHN	MOND, VA	23226	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETIC DATE
K 363	This REQUIREMENT is not met as evidenced by: Surveyor: 39900 Based upon observations of all corridor doors there are doors found that did not have positive latching that could allow smoke to pass through the doors.  Findings include: On 9/4/2018, between 9:30am and 12:30pm, it was observed that patient room door number 121 not latching when shut.	K 363		
SS=D	Subdivision of Building Spaces - Smoke Barrie CFR(s): NFPA 101  Subdivision of Building Spaces - Smoke Barrier Construction 2012 EXISTING Smoke barriers shall be constructed to a 1/2-hour fire resistance rating per 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke barrier.  19.3.7.3, 8.6.7.1(1) Describe any mechanical smoke control system in REMARKS. This REQUIREMENT is not met as evidenced by: Surveyor: 39900 Based upon observations the fire rated smoke barrier walls have penetrations, joints and openings that are not fire stopped and could allow smoke to pass from one side of the smoke barrier to the other side.	K 372	<ol> <li>The penetration opening in the fire wall was sealed with Fire Caulk the day of survey.</li> <li>All Fire Wall partitions have been inspected and no other penetrations were noted.</li> <li>Inspections of fire wall penetrations will take place subsequent to any construction or new wire cabling by Maintenance to insure all are sealed properly.</li> <li>Monitoring for ongoing compliance as addressed in #3.</li> </ol>	9-4-18

TMENT OF HEALTH	AND HUMAN SERV	VICES VICES			FOI	ed: 09/13/20 RM APPROVI
NT OF DEFICIENCIES N OF CORRECTION	(X1) PROVIDER/SUPPLIE	R/CLIA	(X2) MULTIF A. BUILDING	PLE CONSTRUCTION G 01 - BUILDING 01	(X3) DATE	IO. 0938-03
	495391		B. WING			
PROVIDER OR SUPPLIER		STREET ADD	RESS, CITY, S'	TATE, ZIP CODE	09/	04/2018
URNIE REHAB & NU	IRSING CENTER	1901 LI	BBIE AVE			
(EACH DEFICIENCY MUST	BE PRECEDED BY FILL I	S REGULATORY	ID PREFIX TAG	CROSS-REFERENCED TO THE		(X5) COMPLETION DATE
On 9/4/2018, betwee was observed that the smoke barrier wall a	en 9:30am and 12:3 here was a penetrati bove the celling at c	on in the	K 372	DEFICIENCY)		
	PROVIDER OR SUPPLIER URNIE REHAB & NU  SUMMARY STY  (EACH DEFICIENCY MUST OR LSC IDE  Continued From pa On 9/4/2018, between was observed that the smoke barrier wall as	PROVIDER OR SUPPLIER URNIE REHAB & NURSING CENTER  SUMMARY STATEMENT OF DEFICIENCIES OR LSC IDENTIFYING INFORMATION)  Continued From page 8  On 9/4/2018, between 9:30am and 12:31 was observed that there was a penetratic smoke barrier wall above the ceiling at communication.	PROVIDER OR SUPPLIER  URNIE REHAB & NURSING CENTER  SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	RS FOR MEDICARE & MEDICAID SERVICES  NT OF DEFICIENCIES OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  495391  STREET ADDRESS, CITY, S  1901 LIBBIE AVE RICHMOND, VA 2  (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)  Continued From page 8  On 9/4/2018, between 9:30am and 12:30pm, it was observed that there was a penetration in the smoke barrier wall above the ceiling at cross	TOF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  495391  PROVIDER OR SUPPLIER  URNIE REHAB & NURSING CENTER  STREET ADDRESS, CITY, STATE, ZIP CODE  1901 LIBBIE AVE RICHMOND, VA 23226  (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)  Continued From page 8  On 9/4/2018, between 9:30am and 12:30pm, it was observed that there was a penetration in the smoke barrier wall above the ceiling at cross	RS FOR MEDICARE & MEDICAID SERVICES  NT OF DEFICIENCIES IDENTIFICATION NUMBER:  495391  PROVIDER OR SUPPLIER  URNIE REHAB & NURSING CENTER  STREET ADDRESS, CITY, STATE, ZIP CODE  1901 LIBBIE AVE RICHMOND, VA 23226  SUMMARY STATEMENT OF DEFICIENCIES OR LISC IDENTIFYING INFORMATION)  CEACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)  Continued From page 8  On 9/4/2018, between 9:30am and 12:30pm, it was observed that there was a penetration in the smoke barrier wall above the ceiling at cross