

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 05/03/2018  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>495243</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/18/2016</b>
NAME OF PROVIDER OR SUPPLIER  <b>ENVOY OF STAUNTON, LLC</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>512 HOUSTON STREET</b> <b>STAUNTON, VA 24402</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>INITIAL COMMENTS</p> <p>Construction Description: Type II(222)</p> <p>The facility is three stories of noncombustible construction, Type II(222) built in 1967. The walls are metal studs with drywall. The roof is a one-hour fire rated roof/ceiling assembly with steel bar joists and a 1-hour, lay-in tile ceiling assembly, complete with tented lights and speakers, and fire dampers. The floors are 2-hour fire rated ceiling/floor assembly with steel bar joists and a 1-hour lay-in ceiling assembly.</p> <p>Sprinkler status: The building is fully protected by NFPA 13 systems supplied by municipal water.</p> <p>An unannounced Life Safety Code revisit to the standard survey conducted 06/30/2016 was conducted on 07/18/2016, in accordance with 42 Code of Federal Regulation, Part 483: Requirements for Long Term Care Facilities. The facility was surveyed for compliance using the LSC 2000 Health (Existing) regulations. The facility was in compliance with the Requirements for Participation Medicare and Medicaid.</p> <p>Corrected deficiencies are identified on the CMS-2567B.</p> <p>Construction Description: Type II(222)</p> <p>The facility is a two story addition to the main building of noncombustible construction, Type II(222) built in 1993. The walls are metal studs with drywall. The roof is a one-hour fire rated roof/ceiling assembly with steel bar joists and a 1-hour, lay-in tile ceiling assembly, complete with tented lights and speakers, and fire dampers. The floors are 2-hour fire rated ceiling/floor</p>	{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 05/03/2018  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>495243</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01, 02</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>07/18/2016</b>
NAME OF PROVIDER OR SUPPLIER  <b>ENVOY OF STAUNTON, LLC</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>512 HOUSTON STREET</b> <b>STAUNTON, VA 24402</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>Continued From page 1 assembly with steel bar joists and a 1-hour, lay-in ceiling assembly.</p> <p>Sprinkler status: The building is fully protected by NFPA 13 systems supplied by municipal water.</p> <p>An unannounced Life Safety Code revisit to the standard survey conducted 06/30/16 was conducted on 07/18/2016, in accordance with 42 Code of Federal Regulation, Part 483: Requirements for Long Term Care Facilities. The facility was surveyed for compliance using the LSC 2000 Health (Existing) regulations. The facility was in compliance with the Requirements for Participation Medicare and Medicaid.</p> <p>Corrected deficiencies are identified on the CMS-2567B.</p>	{K 000}			