
Dotting

(Taking off your personal protective equipment)

If bare hands get contaminated during doffing at any point, immediately perform hand hygiene then resume doffing.



GLUVES

Outside of gloves contaminated

- Using one gloved hand, pinch palm area of other gloved hand and peel off first glove
- Hold removed glove in gloved hand
- Using ungloved hand, slide fingers under glove of other hand
- Peel off second glove to enclose grasped first glove
- Discard gloves



EYEPKOIECIION

Outside of eye protection contaminated

- Lift strap from back of head, over top of head
- Clean & disinfect per facility protocol
- Discard if damaged or unable to clean & disinfect






GOWIN

Gown front and sleeves contaminated

- Unfasten gown ties
- Touching inside of gown, pull gown away from neck and shoulders
- Turn gown inside out
- Fold into bundle
- Discard gown



MASK

Mask front contaminated

- Remove band at neck first, until or lift over top of head
- Untie or remove band on head second
- Grasp ear loops and remove
- Discard mask or respirator





