

# COMMONWEALTH of VIRGINIA DEPARTMENT OF HEALTH DIVISION OF SHELLFISH SANITATION

Marissa J. Levine, MD, MPH, FAAFP State Health Commissioner 109 Governor Street, 6<sup>th</sup> Floor P.O. Box 2448 Richmond, Virginia 23218

Ph: 804-864-7487 Fax: 804-864-7481

# OCEAN VIEW – WILLOUGHBY Growing Area # 067 Shoreline Sanitary Survey City of Norfolk

Date: 22 November 2016

Survey Period: October 21, 2016

Total Number of Properties Surveyed: 0

Surveyed By: L.M. Sakach

**SECTION A: GENERAL** 

This survey area extends from Reference Point 68 at the western end of the Hampton Roads Bridge Tunnel (east end of Ocean View Avenue) to Reference Point 69 located at the end of Chesapeake Street extending to the waters edge, including all of the southern Chesapeake Bay shoreline between these two points.

The topography of the area is predominately flat with elevations not exceeding 15-20 feet. The survey area is almost entirely residential with some commercial development located along Ocean View Avenue. The entire area is served by Hampton Road Sanitation District (HRSD) sewage system. The economy of the area is based on local service industries, military installations and seasonal water recreation.

There was 0.02" of rainfall on the day of the survey.

There are currently no restrictions on shellfish harvesting in the survey area. Copies of Bacteriological, Hydrographic and Shellfish Closure data are available at the area office for review. Copies of the current condemnation notices and maps are available via the Internet at <a href="https://www.vdh.virginia.gov/shellfish/">www.vdh.virginia.gov/shellfish/</a>.

This report lists only those properties that have a sanitary deficiency or have other environmental significance. "*DIRECT*" indicates that the significant activity or deficiency has a direct impact on shellfish waters. Individual field forms with full information on properties listed in this report are on file in the Richmond Office of the Division of Shellfish Sanitation and are available for reference until superseded by a subsequent survey of the area. Data in the report is also made available to local health departments and other agencies to address items that may be out of compliance with their regulatory programs.

There were no deficiencies or significant properties documented with this survey.



## **SECTION B: SEWAGE POLLUTION SOURCES**

# SEWAGE TREATMENT FACILITIES

-None-

## **ON-SITE SEWAGE DEFICIENCIES**

-None-

**SECTION C: NON-SEWAGE WASTE SITES** 

**INDUSTRIAL WASTES** 

-None-

**SOLID WASTE DUMPSITES** 

-None-

**SECTION D: BOATING ACTIVITY** 

**MARINAS** 

-None-

OTHER PLACES WHERE BOATS ARE MOORED

-None-

**UNDER SURVEILLANCE** 

-None-

**SECTION E: CONTRIBUTES ANIMAL POLLUTION** 

-None-

#### SUMMARY

Growing Area # 067 Ocean View-Willoughby 21 November 2016

#### **SECTION B: SEWAGE POLLUTION SOURCES**

- 1. SEWAGE TREATMENT FACILITIES
  - 0 DIRECT None.
  - 0 INDIRECT None.
  - 0 B.1. TOTAL
- **2. ON-SITE SEWAGE DEFICIENCIES** Correction of the deficiencies in this section is the responsibility of the local health department.
  - 0 CONTRIBUTES POLLUTION, DIRECT None.
  - 0 CONTRIBUTES POLLUTION, INDIRECT None.
  - 0 CP (Kitchen or Laundry Wastes), DIRECT None.
  - 0 CP (Kitchen or Laundry Wastes), INDIRECT None.
  - 0 NO FACILITIES, DIRECT None.
  - 0 NO FACILITIES, INDIRECT None.
  - 0 B.2. TOTAL
- **3. POTENTIAL POLLUTION** Periodic surveillance of these properties will be maintained to determine any status change.
  - 0 POTENTIAL POLLUTION None.

#### **SECTION C: NON-SEWAGE WASTE SITES**

- 1. INDUSTRIAL WASTE SITES
  - 0 DIRECT None.
  - 0 INDIRECT None.
  - 0 C.1. TOTAL

#### 2. SOLID WASTE DUMPSITES

- 0 DIRECT None.
- <u>0</u> INDIRECT None.
- 0 C.2. TOTAL

#### **SECTION D: BOATING ACTIVITY**

- 0 MARINAS None.
- 0 OTHER PLACES WHERE BOATS ARE MOORED None.
- <u>0</u> UNDER SURVEILLANCE None.
- 0 D. TOTAL

#### SECTION E: CONTRIBUTES ANIMAL POLLUTION

- 0 DIRECT None.
- <u>0</u> INDIRECT None.
- 0 E. TOTAL

